HOLDEN'S SCREEN SUPPLY CORPORATION

121 VARICK STREET, NEW YORK, NY 10013 1-800-221-2697

Section 1 Identification

Product Name AquaBrite® Water Based Inks
Chemical Name & Synonyms Synthetic pigment disbursed in water

Chemical Family Polymer

Formula Long chain prepolymers

Section 2 Hazardous Ingredients %

Material Ammonium Hydroxide 1.4 TLV 50 PPM

Section 3Physical DataBoiling Point $200^{0}F - 210^{0}F$

Vapor Pressure (mm Hg) N/A Vapor Density (Air = 1.00) 0.90 Specific Gravity ($H_2O = 1.00$) N/A Solubility in Water Soluble

Appearance and Odor Usual colors and ammonia smell

Melting Point N/A
Evaporation Rate N/A

Section 4 Fire & Explosion Hazard Data

Flash Point and Method
Flammable Limits
None
Extinguishing Media
None
Special Fire Fighting Procedures
Unusual Fire & Explosion Hazards
None

Section 5 Reactivity Data

Stability Stable Materials to avoid None

Hazardous decomposition products CO and Nitrogen Hazardous polymerization Will not occur

Section 6 Health Hazard Data

Effects of Overexpsure Inhalation: Anesthetic, irritation of the respiratory tract

or acute nervous system depression characterized by headaches, dizziness, staggering gait, confusion,

unconsciousness or coma.

Health Hazards None

Emergency & First Aid Procedures Fumes: remove from exposure. Restore breathing. Keep

warm and quit. Notify physician.

Emergency and first aid procedures

For skin contact Wash eyes, and skin with large amounts of water. If

irritation persists, get medical attention.

Inhalation Removed to fresh air. If symptoms persist, get medical

attention.

If swallowed Drink large amounts of milk. Call physician

immediately.

HOLDEN'S SCREEN SUPPLY CORPORATION

121 VARICK STREET, NEW YORK, NY 10013 1-800-221-2697

Section 7 Precautions for safe handling & use

Steps to be taken in case of spill Remove all sources of ignition (flames, hot surfaces, and

electrical, static or frictional sparks). Avoid breathing

vapors. Ventilate area.

Waste disposal method Dispose of in accordance with all existing local, state,

and federal ordinances

Section 8 Control Measures

Respiratory Use bureau of mines respirators

Ventilation Local

Protective gloves Recommended

Eye protection Safety glasses, goggles, or face shield

Other protective clothing As required

Section 9 Special Precautions

Handling & Storing

Do not store above 120°F. Protect from freezing.